

REPORT**Excavators**

MAKE	KOMATSU	MODEL	PC128UU-1	SERIAL #	5255
HOUR/KM	6333Hrs	YEAR	2000	DATE	15-Jun-09

EVALUATION

Appearance	Dents in the side cover & upper frame; partial repaint	HYD Pump	Oil seepage
Cabin/CNP	CAB - minor dents	Swivel Joint	OK
Battery	OK	Control Valve	OK
Engine	Minor blow-by	Swing Bearing	Minor rattle
Radiator	OK	Travel Motor (L)	OK
Oil Cooler	OK	Travel Motor (R)	OK

SPECIFICATION & ATTACHMENT

ENGINE MODEL	-	MULTI PATTERN V	Yes
ENGINE No	-	ARM CRANE	-
USA EPA	Yes	PIPING	-
BLADE	Yes, dented	SHOE TYPE	Roadliner
AIR CONDITIONER	Yes	SHOE WIDTH	500 mm
REMARKS			

OIL LEAK FROM CYLINDER

BOOM	OK	ARM	OK	BUCKET	OK
OFF SET	OK	BLADE	OK		

UNDER CARRIAGE CONDITION (Remaining Value%)

SHOE L	20%	LINK L	60%	BUSH L	60%	IDLER L	50%	SPROCKET L	60%
R	20%	R	60%	R	60%	R	50%	R	60%
CARRIER ROLLER L	40%			TRACK ROLLER L	30%				
	40%				R	20%			

REMARKS

* Minor dents in the tip of the arm