

REPORT**Mini Excavators**

MAKE	YANMAR	MODEL	Vio30-1	SERIAL #	12806B
HOUR/KM	3254 Hrs	YEAR	1999	DATE	1-Dec-07

EVALUATION

Appearance	Dents in the upper frame and radiator cover	HYD Pump	Oil seepage from near pump connection
Cabin/CNP	CNP – OK	Swivel Joint	Not checked due to cover
Battery	OK	Control Valve	Not checked due to cover
Engine	OK	Swing Bearing	OK
Radiator	OK	Travel Motor (L)	OK
Oil Cooler	OK	Travel Motor (R)	OK

SPECIFICATION & ATTACHMENT

ENGINE MODEL	–	MULTI PATTERN V	Yes
ENGINE No	–	ARM CRANE	–
USA EPA	–	PIPING	–
BLADE	Yes	SHOE TYPE	Rubber
AIR CONDITIONER	–	SHOE WIDTH	300 mm
REMARKS			

OIL LEAK FROM CYLINDER

BOOM	Oil leakage	ARM	OK	BUCKET	OK
OFF SET	–	BLADE	OK		

UNDER CARRIAGE CONDITION (Remaining Value%)

SHOE L	%	LINK L	%	BUSH L	%	IDLER L	60%	SPROCKET L	40%
R	%	R	%	R	%	R	60%	R	40%
CARRIER ROLLER L				40%		TRACK ROLLER L			40%
R				30%		R			40%
RUBBER SHOE L				90%		RUBBER SHOE R			20%

REMARKS

* Bucket is worn thin in areas – Please see photos