

REPORT**Carrier**

MAKE	YANMAR	MODEL	C30R-1	SERIAL	10777C
HOUR	1338 Hrs	YEAR	1998	DATE	2009.04.17

EVALUATION

Appearance	Lots of dents	HYD Pump	OK
Cabin	Seat is ripped	Control Valve	OK
Battery	OK	Travel Motor (L)	OK
Engine	OK	Travel Motor (R)	OK
Radiator	OK	Vessel	Dents, few cracks
Oil Cooler	-	Parking Brake	OK

SPECIFICATION & ATTACHMENT

ENGINE MODEL	-	SHOE TYPE	Rubber
USA EPA	-	SHOE WIDTH	300 mm
AIR CONDITIONER	-		
REMARKS			

OIL LEAK FROM CYLINDER

Vessel	OK				
--------	----	--	--	--	--

UNDER CARRIAGE CONDITION (Remaining Value%)

SHOE L	%	LINK L	%	BUSH L	%	IDLER L	30%	SPROCKET L	30%
R	%	R	%	R	%	R	30%	R	30%
CARRIER ROLLER L				30%	TRACK ROLLER L				30%
R				30%	R				30%
RUBBER SHOE L				80%	RUBBER SHOE R				60%

REMARKS