

REPORT**Mini Excavators**

MAKE	KUBOTA	MODEL	K-005	SERIAL #	10232
HOUR/KM	1031 Hrs	YEAR	1999	DATE	18-Jul-08

EVALUATION

Appearance	scratches, dents and bends	HYD Pump	OK
Cabin/CNP	Seat is ripped	Swivel Joint	OK
Battery	OK	Control Valve	OK
Engine	OK	Swing Bearing	OK
Radiator	-	Travel Motor (L)	OK
Oil Cooler	-	Travel Motor (R)	OK

SPECIFICATION & ATTACHMENT

ENGINE MODEL	-	MULTI PATTERN V	-
ENGINE No	714281	ARM CRANE	-
USA EPA	-	PIPING	-
BLADE	OK	SHOE TYPE	Rubber
AIR CONDITIONER	-	SHOE WIDTH	150 mm
REMARKS			

OIL LEAK FROM CYLINDER

BOOM	OK	ARM	OK	BUCKET	OK
OFF SET	OK	BLADE	OK		

UNDER CARRIAGE CONDITION (Remaining Value%)

SHOE L	%	LINK L	%	BUSH L	%	IDLER L	70%	SPROCKET L	70%
R	%	R	%	R	%	R	70%	R	70%
CARRIER ROLLER L	%			TRACK ROLLER L			70%		
R	%			R			70%		
RUBBER SHOE L	70%			RUBBER SHOE R			100%		

REMARKS

Inspected by UV